

# Fundamentals of Metal Forming

1. Overview
2. Material Behavior
3. Temperature Effects
4. Strain Rate Effect
5. Friction and Lubrication

# Introduction

- Metal Forming uses plastic deformation to change the shape of metal workpieces
  - Materials (metals) – plastic deformation
  - External loads – Typically compressive
    - Sometimes **Stretch** the metal (*tensile*), **bend** the metal (*tensile and compressive*), **shear** stresses
  - Shape - die and tools
- Classification
  - Bulk Deformation
  - Sheet Metal Forming – High surface area-to-volume ratio
    - Parts are called *stampings*
    - Usual tooling: *punch* and *die*






# Introduction

- Bulk Deformation Process


- Rolling
- **Forging**
- Extrusion
- Drawing

- Sheet metal forming

- Bending
- Drawing
- Shearing
- (Stamping)



# Forging Sequence of Part and Die



**FIGURE 9.35**

Stages in the formation of a crankshaft by hot forging from bottom to top (Courtesy of National Machinery LLC).



**FIGURE 9.33**

Hand-fed crankshaft progressive die used on a 3000-ton press (Courtesy of National Machinery LLC).

# Material Properties in Forming

- Desirable material properties:
  - *Yield strength ?*
  - *Ductility ?*
  - *Second phase or Inclusion ?*
- These properties are affected by *temperature*:
  - When work temperature is raised, ductility increases and yield strength decreases while loosing on surface finish and dimension accuracy.
- Other factors:
  - Strain rate and friction


# Theories of Failure

- The limit of the stress state on a material
  - Ductile Materials - Yielding
  - Brittle Materials - Fracture
- In a tensile test, Yield or Failure Strength of a material.
- In a multiaxial state of stress, how do we use Yield or Failure Strength?

# Yielding: Ductile Materials

## A. Maximum Shear Stress Theory (Tresca Criterion)

In a tension specimen:  $\tau_{\max} = \frac{S_y}{2}$



The diameter of the Mohr circle =  $S_y$

For **Plane** Stress:  $|\sigma_1| = S_y$   
 $(\sigma_3=0)$   $|\sigma_2| = S_y$   $\left. \vphantom{\begin{matrix} |\sigma_1| = S_y \\ |\sigma_2| = S_y \end{matrix}} \right\} \sigma_1, \sigma_2 \text{ have same signs.}$   
 $|\sigma_1 - \sigma_2| = S_y$   $\left. \vphantom{|\sigma_1 - \sigma_2| = S_y} \right\} \sigma_1, \sigma_2 \text{ have opposite signs.}$

# Ductile Materials

## B. Maximum Distortion Energy Theory (von Mises Criterion)

For the three principal stresses;

$$u = \frac{1}{2}[\sigma_1 \varepsilon_1 + \sigma_2 \varepsilon_2 + \sigma_3 \varepsilon_3] = \frac{1}{2E}[\sigma_1^2 + \sigma_2^2 + \sigma_3^2 - 2\nu(\sigma_1 \sigma_2 + \sigma_3 \sigma_2 + \sigma_1 \sigma_3)]$$

After taken out the hydrostatic stress ( $\sigma_{ave} = (\sigma_1 + \sigma_2 + \sigma_3)/3$ )

Now substitute  $\sigma_1$ ,  $\sigma_2$  and  $\sigma_3$  with  $(\sigma_1 - \sigma_{ave})$ ,  $(\sigma_2 - \sigma_{ave})$ ,  $(\sigma_3 - \sigma_{ave})$


For plane stress;  $u_d = \frac{1+\nu}{3E}[\sigma_1^2 - \sigma_1 \sigma_2 + \sigma_2^2]$

$$u_d = \frac{1+\nu}{3E} S_y^2 \text{ in an uniaxial tension test.}$$

In a biaxial case, the same amount of distortion energy

$$\frac{1+\nu}{3E}[\sigma_1^2 - \sigma_1 \sigma_2 + \sigma_2^2] = \frac{1+\nu}{3E} S_y^2$$

$$\sigma_1^2 - \sigma_1 \sigma_2 + \sigma_2^2 = S_y^2$$






# Plasticity


- Flow theory (Classical theory)
  - The current strain rates depend on the stress.
- Deformation theory (Hencky theory)
  - The total strain is related to the stress.
  - Ideal for nonlinear elasticity
  - Still work for monotonically increasing stresses everywhere in a body
- Pressure-independent – Hydrostatic pressure does not affect dislocation motion.
- Bauschinger effect
  - The different behaviors in tension and compression

# Stress Representation

General 3-D Stress



Plane Stress



Tensor Notation

$$\begin{bmatrix} \sigma_x & \tau_{xy} & \tau_{xz} \\ \tau_{xy} & \sigma_y & \tau_{yz} \\ \tau_{xz} & \tau_{yz} & \sigma_z \end{bmatrix} = \begin{bmatrix} \sigma_{11} & \sigma_{12} & \sigma_{13} \\ \sigma_{21} & \sigma_{22} & \sigma_{23} \\ \sigma_{31} & \sigma_{32} & \sigma_{33} \end{bmatrix} = \sigma_{ij}$$

$$\begin{bmatrix} \sigma_x & \tau_{xy} & 0 \\ \tau_{xy} & \sigma_y & 0 \\ 0 & 0 & 0 \end{bmatrix} = \sigma_{ij}$$

# Stress Transformation (Plane Stress)

$$\begin{aligned}\sigma_{x'} &= \frac{\sigma_x + \sigma_y}{2} + \frac{\sigma_x - \sigma_y}{2} \cos 2\theta + \tau_{xy} \sin 2\theta \\ \tau_{x'y'} &= -\frac{\sigma_x - \sigma_y}{2} \sin 2\theta + \tau_{xy} \cos 2\theta \\ \sigma_{y'} &= \frac{\sigma_x + \sigma_y}{2} - \frac{\sigma_x - \sigma_y}{2} \cos 2\theta - \tau_{xy} \sin 2\theta\end{aligned}$$

$$\begin{aligned}\sigma_{x'} + \sigma_{y'} &= \frac{\sigma_x + \sigma_y}{2} + \frac{\sigma_x - \sigma_y}{2} \cos 2\theta + \tau_{xy} \sin 2\theta + \frac{\sigma_x + \sigma_y}{2} - \frac{\sigma_x - \sigma_y}{2} \cos 2\theta - \tau_{xy} \sin 2\theta = \sigma_x + \sigma_y \\ -\sigma_{x'} \sigma_{y'} + \tau_{x'y'}^2 &= -\left( \frac{\sigma_x + \sigma_y}{2} + \frac{\sigma_x - \sigma_y}{2} \cos 2\theta + \tau_{xy} \sin 2\theta \right) \left( \frac{\sigma_x + \sigma_y}{2} - \frac{\sigma_x - \sigma_y}{2} \cos 2\theta - \tau_{xy} \sin 2\theta \right) + \left( -\frac{\sigma_x - \sigma_y}{2} \sin 2\theta + \tau_{xy} \cos 2\theta \right)^2 \\ &= -\left( \frac{\sigma_x + \sigma_y}{2} \right)^2 + \left( \frac{\sigma_x - \sigma_y}{2} \cos 2\theta + \tau_{xy} \sin 2\theta \right)^2 + \left( -\frac{\sigma_x - \sigma_y}{2} \sin 2\theta + \tau_{xy} \cos 2\theta \right)^2 \\ &= \left( \frac{\sigma_x + \sigma_y}{2} \right)^2 - \left( \frac{\sigma_x - \sigma_y}{2} \cos 2\theta + \tau_{xy} \sin 2\theta \right)^2 + \left( -\frac{\sigma_x - \sigma_y}{2} \sin 2\theta + \tau_{xy} \cos 2\theta \right)^2 \\ &= -\sigma_x \sigma_y + \tau_{xy}^2\end{aligned}$$

# Yield function in 3D

Stress Tensor :  $[\sigma_{ij}] = [\sigma'_{ij} + \sigma_m \delta_{ij}]$

where  $\sigma'_{ij}$  = Deviatoric Stress Tensor,

$$\sigma_m = \frac{1}{3}(\sigma_1 + \sigma_2 + \sigma_3) = \text{Hydrostatic Component of Stress}$$

$$\delta_{ij} = 1 \quad \text{for } i = j$$

$$0 \quad \text{for } i \neq j$$

Three Stress Invariants

$$\sigma^3 - I_1 \sigma^2 - I_2 \sigma - I_3 = 0$$

where  $I_1 = \sigma_x + \sigma_y + \sigma_z = \sigma_1 + \sigma_2 + \sigma_3$

$$\begin{aligned} I_2 &= -(\sigma_x \sigma_y + \sigma_y \sigma_z + \sigma_x \sigma_z) + \tau_{xy}^2 + \tau_{yz}^2 + \tau_{zx}^2 \\ &= -(\sigma_1 \sigma_2 + \sigma_3 \sigma_2 + \sigma_3 \sigma_1) \end{aligned}$$

$$\begin{aligned} I_3 &= \sigma_x \sigma_y \sigma_z + 2\tau_{xy} \tau_{yz} \tau_{xz} - \sigma_x \tau_{yz}^2 - \sigma_y \tau_{xz}^2 - \sigma_z \tau_{xy}^2 \\ &= \sigma_1 \sigma_2 \sigma_3 \end{aligned}$$

Three Deviatoric Stress Invariants

$$\sigma'^3 - J_1 \sigma'^2 - J_2 \sigma' - J_3 = 0$$

where  $J_1 = 0$


$$J_2 = -(\sigma'_1 \sigma'_2 + \sigma'_3 \sigma'_2 + \sigma'_3 \sigma'_1)$$

$$J_3 = \sigma'_x \sigma'_y \sigma'_z$$

Yield function:  $f(\sigma_{ij}) = f(\sigma_I) = f(I_1, I_2, I_3) = f(J_2, J_3) = C$

# Example: Stresses in 3D

$$[\sigma_{ij}] = \begin{bmatrix} \sigma_{11} & \sigma_{21} & \sigma_{31} \\ \sigma_{12} & \sigma_{22} & \sigma_{32} \\ \sigma_{13} & \sigma_{23} & \sigma_{33} \end{bmatrix} = \begin{bmatrix} \sigma_x & \tau_{yx} & \tau_{zx} \\ \tau_{xy} & \sigma_y & \tau_{zy} \\ \tau_{xz} & \tau_{yz} & \sigma_z \end{bmatrix}$$



To find Principal Stresses:

$$[\sigma_{ij}] = \begin{bmatrix} 5 & -1 & -1 \\ -1 & 4 & 0 \\ -1 & 0 & 4 \end{bmatrix} \text{ MPa}$$

$$\begin{vmatrix} 5 - \sigma & -1 & -1 \\ -1 & 4 - \sigma & 0 \\ -1 & 0 & 4 - \sigma \end{vmatrix} \begin{bmatrix} n_1 \\ n_2 \\ n_3 \end{bmatrix} = 0$$

$$\begin{aligned} (5 - \sigma)(4 - \sigma)^2 - (4 - \sigma) - (4 - \sigma) &= \\ = (4 - \sigma)(3 - \sigma)(6 - \sigma) &= 0 \end{aligned}$$

$$\sigma^3 - 13\sigma^2 + 54\sigma - 72 = 0$$

$$\sigma_1 = 3 \text{ MPa}, \sigma_2 = 4 \text{ MPa and } \sigma_3 = 6 \text{ MPa}$$

$$I_1 = \sigma_1 + \sigma_2 + \sigma_3 = 13,$$

$$I_2 = -(\sigma_1\sigma_2 + \sigma_3\sigma_2 + \sigma_3\sigma_1) = -(12 + 24 + 18) = -54 \text{ and}$$

$$I_3 = \sigma_1\sigma_2\sigma_3 = 72$$

# Example: Continue

$$[\sigma_{ij}] = \begin{bmatrix} 5 & -1 & -1 \\ -1 & 4 & 0 \\ -1 & 0 & 4 \end{bmatrix} \text{MPa}$$

$$\sigma_{1-3} = 3, 4 \text{ \& } 6 \text{MPa}$$

$$\sigma_m = \frac{1}{3}(5 + 4 + 4) = \frac{1}{3}(3 + 4 + 6) = 4.33 \text{MPa}$$

$$[\sigma'_{ij}] = [\sigma'_{ij} + \sigma_m \delta_{ij}]$$

$$\sigma'_{ij} = \begin{bmatrix} 5 & -1 & -1 \\ -1 & 4 & 0 \\ -1 & 0 & 4 \end{bmatrix} - \begin{bmatrix} 4.33 & 0 & 0 \\ 0 & 4.33 & 0 \\ 0 & 0 & 4.33 \end{bmatrix}$$

$$= \begin{bmatrix} 0.67 & -1 & -1 \\ -1 & -0.33 & 0 \\ -1 & 0 & -0.33 \end{bmatrix}$$

Deviatoric Stress

$$\begin{bmatrix} 0.67 - \sigma' & -1 & -1 \\ -1 & -0.33 - \sigma' & 0 \\ -1 & 0 & -0.33 - \sigma' \end{bmatrix}$$

$$(0.33 + \sigma')^2(0.67 - \sigma') + 2(0.33 + \sigma') = 0$$

$$(0.33 + \sigma') \left( \frac{20}{9} + \frac{1}{3} \sigma' - \sigma'^2 \right) = 0$$

$$0.74 + 2.33\sigma' - \sigma'^3 = 0$$

$$J_1 = 0; J_2 = -2.33; J_3 = 0.74$$

# Presentation of Yield Surface

Max. Shear Stress Theory:  $f(\sigma_{1,2,3}) = \sigma_1 - \sigma_3 = C$

$$f(J_2, J_3) = 4J_2^3 - 27J_3^2 - 36k^2J_2^2 + 96k^4J_2 - 64k^6 = C$$

Maximum Distortion Energy Theory:  $f(J_2, J_3) = J_2 = k^2 = C$

$$f(\sigma_{1,2,3}) = J_2 = \frac{1}{6}[(\sigma_1 - \sigma_2)^2 + (\sigma_2 - \sigma_3)^2 + (\sigma_3 - \sigma_1)^2] = C$$

Max. Shear Stress Theory

Maximum Distortion Energy Theory

Based on uniaxial yielding:  $\sigma_1 = \sigma, \sigma_2 = \sigma_3 = 0$


$$\begin{aligned} f(\sigma_{1,2,3}) &= \sigma_1 - \sigma_3 = C \\ S_y &= C \end{aligned}$$

$$\begin{aligned} f(J_2, J_3) &= J_2 = \frac{1}{6}(\sigma^2 + \sigma^2) = C; \\ C &= \frac{\sigma^2}{3} = \frac{S_y^2}{3} \end{aligned}$$




For shear:  $\sigma_1 = -\sigma, \sigma_2 = \sigma, \sigma_3 = 0$

$$\begin{aligned} f(\sigma_{1,2,3}) &= 2\sigma = C = S_y; \\ \sigma &= \frac{S_y}{2} \end{aligned}$$

$$\begin{aligned} f(J_2, J_3) &= J_2 = \frac{1}{6}(4\sigma^2 + \sigma^2 + \sigma^2) = C; \\ \sigma &= \frac{S_y}{\sqrt{3}} \end{aligned}$$



# Plasticity



Plastic State:  $f(\sigma_{ij}) = 0$

Elastic State:  $f(\sigma_{ij}) < 0$

Impossible:  $f(\sigma_{ij}) > 0$

Loading:  $f(\sigma_{ij}) = C, \quad df = \frac{\partial f}{\partial \sigma_{ij}} \sigma_{ij} > 0$


Unloading:  $f(\sigma_{ij}) = C, \quad df = \frac{\partial f}{\partial \sigma_{ij}} \sigma_{ij} < 0$

Neutral:  $f(\sigma_{ij}) = C, \quad df = \frac{\partial f}{\partial \sigma_{ij}} \sigma_{ij} = 0$




# Strain Hardening


Isotropic Hardening



Kinematics Hardening




Convexity




Normality Rule:

$$d\varepsilon_{ij} = d\lambda \frac{\partial f}{\partial \sigma_{ij}}$$



Combined Hardening



General Hardening

## 2. Behavior in Metal Forming

- The stress-strain relationship beyond elastic range assuming no unloading at anytime and anywhere.

$$\sigma = K\varepsilon^n$$


- Flow stress – The instantaneous value of stress required to continue deforming the material.

$$Y_f = K\varepsilon^n$$

- Average Flow Stress

$$\bar{Y}_f = \frac{\int_0^{\varepsilon_f} \sigma d\varepsilon}{\varepsilon_f} = \frac{\int_0^{\varepsilon_f} K\varepsilon^n d\varepsilon}{\varepsilon_f} = \frac{K\varepsilon_f^n}{1+n}$$

- For any metal,  $K$  and  $n$  in the flow curve depend on temperature



# 3. Temperature in Metal Forming

- Cold Working – Performed at room temperature or slightly above
  - *Near net shape or net shape*
  - Better accuracy, closer tolerances & surface finish
  - Strain hardening increases strength and hardness
  - Grain flow during deformation can cause desirable directional properties in product
  - No heating of work required
  - Higher forces and power required
  - Surfaces must be free of scale and dirt
  - Ductility and strain hardening limit the amount of forming

# Warm Working

- Performed at above room temperature but below recrystallization temperature
- $0.3T_m$ , where  $T_m$  = melting point (absolute temperature)
  - Lower forces and power than in cold working
  - More intricate work geometries possible
  - Need for annealing may be reduced or eliminated
- Isothermal Forming – eliminate surface cooling especially highly alloyed steels and Ti and Ni alloys


# Hot Working

- Deformation process at temperatures above *recrystallization temperature* ( $0.5 T_m$ )
- A perfectly plastic material - Strain hardening exponent is zero (theoretically)
  - Lower forces and power required
  - Metals become ductile
  - Strength properties are generally isotropic
  - No work hardening of part
  - part can be subsequently cold formed
  - Lower dimensional accuracy
  - Higher total energy required
  - Poorer surface finish including oxidation (scale),
  - Shorter tool life

## 4. Effect of Strain Rate

- Sensitive to strain-rate at elevated temperatures
- Strain rate:  $\dot{\epsilon} = \frac{v}{h}$
- Relationship:  $Y_f = C \dot{\epsilon}^m$
- A more complete relationship:  $Y_f = A \epsilon^n \dot{\epsilon}^m$
- Evaluation of strain rate is complicated by
  - Workpart geometry
  - Variations in strain rate on the part
- Strain rate can reach  $1000 \text{ s}^{-1}$  or more for some metal forming operations

# Effect of temperature on flow stress



Increasing temperature decreases  $C$  & increases  $m$

At room temperature, effect of strain rate is almost negligible

# 5. Friction and Lubrication

- Friction – retard metal flow and increase power and wear

Categories	Temp. Range	Strain-rate Sensitivity exponent	Coefficient of Friction
Cold Working	$<0.3T_m$	$0 < m < 0.05$	0.1
Warm Working	$0.3T_m - 0.5T_m$	$0.05 < m < 0.1$	0.2
Hot Working	$0.5T_m - 0.75T_m$	$0.05 < m < 0.4$	0.4-0.5

- Lubrication – reduce friction & heat, improve surface finish
  - Choosing a Lubricant – Type of operation, reactivity, work materials, cost and ease of applications
    - Cold working – mineral oil, fats, fatty oils, water-based emulsions, soaps and coating
    - Hot working – mineral oil, graphite and glass